

P04 9037166

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED—
NOT FOR INTERNATIONAL MAIL
(See Reverse)

SENT TO		Larry E. Schell	
STREET ADDRESS		Professional Rebuilders 2800 W. Battlefield Rd.	
P.O. STATE AND ZIP CODE		Springfield, MO 65807	
POSTAGE		\$	
CONSULT POSTMASTER FOR FEES	OPTIONAL SERVICES	CERTIFIED FEE	c
		SPECIAL DELIVERY	c
	RETURN RECEIPT SERVICE	RESTRICTED DELIVERY	c
		SHOW TO WHOM AND DATE DELIVERED	c
		SHOW TO WHOM, DATE, AND ADDRESS OF DELIVERY	c
		SHOW TO WHOM AND DATE DELIVERED WITH RESTRICTED DELIVERY	c
		SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY	c
TOTAL POSTAGE AND FEES		\$	
POSTMARK OR DATE			

KC

PS Form 3811, Apr. 1977

RETURN RECEIPT REGISTERED, INSURED AND CERTIFIED MAIL

● SENDER: Complete items 1, 2, and 3. Add your address in the "RETURN TO" space on reverse.		
1. The following service is requested (check one). <input checked="" type="checkbox"/> Show to whom and date delivered c <input type="checkbox"/> Show to whom, date, and address of delivery c <input type="checkbox"/> RESTRICTED DELIVERY Show to whom and date delivered c <input type="checkbox"/> RESTRICTED DELIVERY Show to whom, date, and address of delivery . \$ ____ (CONSULT POSTMASTER FOR FEES)		
2. ARTICLE ADDRESSED TO: Larry E. Schell, President Professional Rebuilders, Inc. 2800 W. Battlefield Rd., Spfd, MO		
3. ARTICLE DESCRIPTION: REGISTERED NO. CERTIFIED NO. INSURED NO. P04 9037166		
(Always obtain signature of addressee or agent)		
I have received the article described above. SIGNATURE <input type="checkbox"/> Addressee <input type="checkbox"/> Authorized agent 4. <i>Larry E. Schell</i>		
DATE OF DELIVERY 8-13-83		POSTMARK
5. ADDRESS (Complete only if requested)		
6. UNABLE TO DELIVER BECAUSE:		CLERK'S INITIALS

August 15, 1983

Mr. Larry E. Schell, President
Professional Rebuilders, Inc.
2800 W. Battleground Rd.
Springfield, MO 65807

Certified No. PO4 9037166

Dear Mr. Schell:

This letter is confirming the meeting Henry Cole and I had with you on Tuesday, August 9, 1983, about your waste holding tank. This office has the following recommendations to make in constructing and maintaining the tank to keep it working efficiently and with safety to the surrounding environment:

- 1.) Coat the inside of the tank with a corrosion resistant epoxy sealer
- 2.) Skim the grease off the top of the tank when necessary
- 3.) Have a septic tank truck pump out the tank as often as necessary to maintain it in good working order
- 4.) Neutralize the contents of the dip tank to a pH of 7, by trickling in acid and mixing it with the contents of the dip tank before discharging them to the holding tank

Personnel from this office will take samples of your holding tank occasionally to ensure that it is working properly.

We also recommend that you attach to the sanitary sewer as soon as it becomes available.

If you have any further questions or problems, please don't hesitate to call 864-1924.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

cc: Henry Cole, P.E., Sanitary Engineer
Robert Schaefer, P.E., Superintendent of Sanitary Services
Burt McCullough, Department of Natural Resources

2800 W. Battleground

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE 8-15-83

DEPARTMENT _____

On Tuesday, August 9, 1983, Henry Cole and I met with Larry Schell, the president of Professional Rebuilders at 2800 W. Battlefield, to inspect their proposed waste holding tank. This tank will hold the waste from their hot engine dipping process. He had built a square basin out of concrete blocks that will hold approximately 2900 gallons. He is going to fill in the blocks with cement, install a fiberglass baffle, and put an elbow into the tank which will drain the water into his existing septic tank. We recommended that he coat the interior of the holding tank with corrosion resistant epoxy sealer and shim off the grease occasionally. Larry Schell said that he dumped his dip tank, which holds 500 gallons, approximately every 4 months. We recommended that he neutralize the waste before discharging it to the holding tank. He uses Zep's formula 9878 to dip the engines. I called the manufacturer in Atlanta who said that this is sodium hydroxide with a little emulsifier in it. The chemist suggested using sulfuric acid as a neutralizer.

cc: Henry Cole, P.E., Sanitary Engineer
Bob Schaefer, Superintendent of Sanitary Services
Burt McCullough, Department of Natural Resources

Karen Chandler
SIGNED Water Pollution Control Inspector II
Surveillance & Enforcement

2800 W. Battlefield

PRI

Larry E. Schell
President

PROFESSIONAL REBUILDERS, INC.

2800 WEST BATTLEFIELD ROAD • SPRINGFIELD, MISSOURI 65807 • (417) 883-7755

RECEIPT FOR CERTIFIED MAIL

P04 9037165

NO INSURANCE COVERAGE PROVIDED—
NOT FOR INTERNATIONAL MAIL

(See Reverse)

PS Form 3800, Apr. 1976

SENT TO Larry E. Schell, President 2800 W. Battlefield Rd. Springfield, MO 65807		P.C. STATE AND ZIP CODE Springfield, MO 65807	
POSTAGE		\$	
CERTIFIED FEE		c	
SPECIAL DELIVERY		c	
RESTRICTED DELIVERY		c	
SHOW TO WHOM AND DATE DELIVERED		c	
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY		c	
SHOW TO WHOM, DATE AND ADDRESS OF DELIVERY WITH RESTRICTED DELIVERY		c	
TOTAL POSTAGE AND FEES		\$	
POSTMARK OR DATE			

PS Form 3811, Apr. 1977 RETURN RECEIPT, REGISTERED, INSURED AND CERTIFIED MAIL

1. The following service is requested (check one). <input checked="" type="checkbox"/> Show to whom and date delivered c <input type="checkbox"/> Show to whom, date, and address of delivery c <input type="checkbox"/> RESTRICTED DELIVERY Show to whom and date delivered c <input type="checkbox"/> RESTRICTED DELIVERY Show to whom, date, and address of delivery \$ ____ (CONSULT POSTMASTER FOR FEES)		2. ARTICLE ADDRESSED TO: Larry E. Schell, President Professional Rebuilders, Inc. 2800 W. Battlefield Rd., Spfld. MO	
3. ARTICLE DESCRIPTION: REGISTERED NO. 1 CERTIFIED NO. 1 INSURED NO. 1 P04 9037165		(Always obtain signature of addressee or agent) I have received the article described above. SIGNATURE <input type="checkbox"/> Addressee <input type="checkbox"/> Authorized agent <i>Larry E. Schell</i>	
4. DATE OF DELIVERY 7-29-83		5. ADDRESS (Complete only if requested) 2800 W. Battlefield Rd.	
6. UNABLE TO DELIVER BECAUSE: INITIALS		POSTMARK SPRINGFIELD 8861 JUL 29 1983	

July 28, 1983

Certified No. PO4 9037165

Mr. Larry E. Schell, President
Professional Rebuilders, Inc.
2800 W. Battlefield Rd.
Springfield, MO 65807

Dear Mr. Schell:

On July 26, 1983, this office received a complaint about a pollutant discharge coming from your business at 2800 W. Battlefield. Personnel from the City's Water Pollution Control Section made a visual inspection of this property and found that the outside plastic pipe that conveyed wastewater from the building to the septic tank had become detached from the building. The wastewater was running out onto the ground beside the building. There was a second pipe in the side of the building that was also apparently discharging onto the ground.

Please be advised that such a discharge is a violation of Federal, State, and City Water Pollution Control Laws and a violation of City Health Ordinances. In particular this is a violation of the City of Springfield's Sewer Use Ordinance, Section 30-4 "Deposit of Objectionable Waste on Public or Private Property Prohibited" and Section 30-8 "Discharge of Sanitary Sewage, Industrial Wastes or Other Polluted Waters into Natural Outlets or Storm Sewers."

Please be further advised that you should reattach the plastic pipe to the drainage pipe in the side of the building and that any other pipes that discharge wastewater must be attached to the septic tank or a separate holding tank.

Enclosed is a copy of Chapter 30, Sewer Use Ordinance. If you have any questions please don't hesitate to call.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

Enclosure

cc: Robert R. Schaefer, P.E., Supt. of Sanitary Services
Henry M. Cole, P.E., Sanitary Engineer
John R. Nixon, Missouri Dept. of Natural Resources
File

2800 W. BATTLEFIELD

JUL 1983

Harvey
Hilton

Reported by	<u>Craig Richardson</u>	<u>Address</u>	<u>Phone</u>
-------------	-------------------------	----------------	--------------

Location of Problem Professional Rebuilder Owner James H. H. H.
Address _____

Condition Reported: pipe carrying caustic fluids to septic tank is

1. $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

Contaminating wells in area. Septic tank is full.

Assigned to: Water Pollution Control By _____ Date 7-26-93

Investigated AM PM By

Conditions found: _____

Action taken: _____

Abatement order issued via _____ Date _____ To be abated by _____

Progress Report made to _____ via _____ Time _____
Date _____

Investigation for compliance	AM PM	By
------------------------------	----------	----

Conditions found: _____

Summons issued to _____ Court date _____

Additional Action Required: _____

Progress report made to _____ via _____ Time _____
Date _____

Reviewed by _____ Remarks _____

2800 W. Battlefield

July 26, 1983

Mr. Leroy Johnston
Professional Rebuilders
2800 W. Battlefield
Springfield, MO 65807

Dear Mr. Johnston:

On July 26, 1983, this office received a complaint about a pollutant discharge coming from your business at 2800 W. Battlefield. Personnel from the City's Water Pollution Control Section made a visual inspection of this property and found that the outside plastic pipe that conveyed wastewater from the building to the septic tank had become detached from the building. This wastewater was running out onto the ground beside the building. There was a second pipe in the side of the building that was also apparently discharging onto the ground.

Please be advised that such a discharge is a violation of Federal, State, and City Water Pollution Control Laws and a violation of City Health Ordinances and must be abated immediately. In particular this is a violation of the City of Springfield's Sewer Use Ordinance, Section 30-4 "Deposit of Objectionable Waste on Public or Private Property Prohibited" which states, "It shall be unlawful for any person to place, deposit, or permit to be deposited in an unsanitary manner upon public or private property within the city or in any area under the jurisdiction of the city any human or animal excrement, garbage or other objectionable waste."

Please be further advised that you should reattach the plastic pipe to the drainage pipe in the side of the building and that any other drainage pipes that discharge wastewater must be attached to the septic tank.

If you have any questions, please don't hesitate to call at 864-1924.

Yours truly,

Karen Chandler
Water Pollution Control Inspector II
Surveillance & Enforcement

KC:js

cc: Robert R. Schaefer, P.E., Supt. of Sanitary Services
Henry M. Cole, P.E., Sanitary Engineer
John R. Nixon, Missouri Dept. of Natural Resources
File

2800 W. Battlefield

July 1, 1982

Mr. Leroy Johnston, Manager
Professional Rebuilders
2800 W. Battlefield
Springfield, Missouri 65807

Dear Mr. Johnston:

On June 30, 1982, this office received a complaint about a pollutant discharge coming from your business at 2800 W. Battlefield. Personnel from the City's Water Pollution Control Section made a visual inspection of this property and found that there was a pipe sticking out of the side of the building discharging wastewater onto your lot. The grass beneath this discharge was dead.

An inspection of the inside of the building revealed that there was no floor drain in the shop going to the septic tank, and that the water going to the outside pipe was water used to wash the engine blocks and to clean up the floor. Please be advised that such a discharge is a violation of Federal, State, and City Water Pollution Control laws, and a violation of City Health Ordinances and must be abated immediately. In particular this is a violation of the City of Springfield's Sewer Use Ordinance Sections: 30-4 "Deposit of Objectionable Waste on Public or Private Property Prohibited"; 30-8 "Discharge of Sanitary Sewage, Industrial Waste or Other Polluted Waters into Natural Outlets or Storm Sewers."

As we discussed yesterday, possible acceptable alternatives to this discharge would be: putting the water into the septic tank; using another septic tank altogether for the shop wastes; or as a strictly temporary measure until your lines to the grease trap and septic tank are installed to contain the water in a leakproof barrel which you could pour into a nearby manhole.

If you have any questions or comments, please don't hesitate to call at 864-1924.

Yours truly,

Karen A. Chandler
Water Pollution Control Inspector II
Surveillance and Enforcement

KAC:js

cc: Robert R. Schaefer, P.E., Superintendent of
Sanitary Services
Henry M. Cole, P.E. Sanitary Engineer
John R. Nixon, Missouri Department of Natural Resources
File

2800 W. Battlefield

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF FILE

DATE July 1, 1982

DEPARTMENT

On Wednesday, June 30, 1982, this office received a citizen's complaint that the Professional Rebuilders at 2800 W. Battlefield was dumping caustic material onto their lot. I observed a pipe coming out of the side of the building, discharging onto the lot. The grass beneath the pipe was dead.

On the inside of the building there was no drain to the septic tank and the water that was going to the pipe was used to wash engine blocks and the floor. I talked to the manager, Leroy Johnston. He said that in a few days the owner was going to install new pipes from the shop that would go to a grease trap, then to the septic tank. I told him that this discharge was a violation of City, State and Federal Water Pollution Control laws and gave him a copy of Chapter 30.

I advised him to either discharge the water to the septic tank or, as a strictly temporary measure, that he could contain it in a barrel beneath the pipe and put it down a nearby manhole.

On July 1, 1982, I checked the pipe at 2800 W. Battlefield and it had been extended and attached to the septic tank on the west side of the building. I delivered the letter to him at this time.

cc: Robert Schaefer, P.E., Superintendent of Sanitary Services
Henry M. Cole, P.E., Sanitary Engineer
File

KB

Karen Chandler

SIGNED Water Pollution Control Inspector II
Surveillance & Enforcement

2800 W. Battlefield